

WEDAC

FOAMING ACID CLEANER

WEDAC is a non-fuming, low odor, high-foaming acid cleaner designed for a variety of applications including aluminum restoration, scale and rust removal, priming metallic surfaces for painting and as an acidic pre-soak in vehicle wash cleaning applications.

WEDAC is effective on many types of metals such as copper, brass, stainless steel, soft metals and aluminum and improves paint and varnish adhesion to primed metal surfaces.

FEATURES & BENEFITS

- High foaming
- Low viscosity
- Water dilutable
- Mild odour
- Inhibited formula available in **KLEEN-EZEY**
- May be used with foaming equipment
- Easily rinsable



DIRECTIONS FOR USE

Use procedure	Apply to surfaces free of excess debris and oils or grease. May be used manually or with an adequate foaming or low-pressure system. Scour or brush stubborn deposits. Re-apply if necessary.
Concentration	Foamer applications, 20:1 to 5:1 or approximately 4 - 17% v/v with water. For acidic pre-soak vehicle wash applications: Low-pressure spray, 100:1 or approximately 0.9 - 1.0% v/v with water. For heavy build-up, more than one application may be required.
Use temperature	Cold to ambient.
Dwell time/Operation time	5 to 15 minutes.
Mechanical action	Scrubbing recommended.
Rinsing	Ensure thorough rinsing with hot or cold water especially with soft metals, cast-iron, galvanized or mild steel.

PHYSICAL PROPERTIES

Appearance	Clear, red liquid
Odour	Faint detergent
Specific gravity @ 20°C	1.4
Viscosity	10 - 30 cps
pH	<1.0
Flash point (TCC)	None
Water solubility	Complete
Boiling point	100°C (212°F)
Freezing point	Not available
Foaming tendency	High
Rinsing	Excellent
Concentration monitoring techniques	Titration, electrical conductivity, refractive index

INCOMPATIBILITY

Bases, organic materials, light metals, bleach

WAREHOUSING PRECAUTIONS

Keep containers tightly closed away from direct sunlight in a dry, cool and well-ventilated place, away from incompatible materials.

AVAILABLE SIZES



4L



20L



205L



1000L



IMPORTANT

Before using **WEDAC**, always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

FIRST AID MEASURES

Eye contact

Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician.

Skin contact

Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse.

Inhalation

Remove victim to fresh air and keep at rest in a position comfortable for breathing. Immediately call a POISON CENTER or doctor/physician.

Ingestion

Do not induce vomiting. Drink 1 or 2 glasses of water. Call a physician or Poison Control Centre immediately. Never give anything by mouth to an unconscious person.

PERSONAL PROTECTION



WHMIS

