WEDAC

FOAMING ACID CLEANER

FOOD INDUSTRY

Food and beverage industry accepted

WEDAC is a high foaming acid descaler. It is designed to remove scale on food and beverage processing equipment. Applied to surfaces where cleaning by circulation is impossible. Also effective on oxidized aluminum to restore its shine.

FEATURES and BENEFITS

- High foaming
- Water dilutable
- Mild odour
- Easy to apply with automatic foaming equipment. Its foam clings to surfaces allowing a longer contact time even at low concentration
- Heavy duty

DIRECTION FOR USE

Equipment to be treated	Stainless steel, aluminum or plastic surfaces.
Depots to nettoyer	Mineral deposit, limestone, magnesium, iron and rust.
Use procedure	Apply manually or with appropriate foaming equipment.
Concentration	0.1% to 10% (1 to 100 ml/l) according to degree of soil.
Use temperature	Between 10ºC and 60ºC (50 ºF to 140 ºF)
Dwell time/Operation time	Between 3 and 25 minutes
Mechanical action	Scrubbing recommended
Rinsing	Rinse with potable water

SEE REVERSE SIDE

WEDAC

Foaming acid cleaner

PHYSICAL PROPERTIES

Appearence	Clear red liquid
Odour	Light
Specific gravity @ 20 °C	1.40
Viscosity	Low
pH to 10%	1.8
Flash point (TCC)	None
Phosphorus	Yes
Water solubility	Complete
Auto ignition temperature	None
Chlorine	None
Boiling point	Approx. 100 °C
Freezing point	< -5 °C
Foaming tendency	High
Concentration monitoring techniques	Titration, electrical conductivity, refractive index
Rinsability	Excellent

INCOMPATIBILITY

Chlorinater and caustic products.

WAREHOUSING PRECAUTIONS

Keep container well closed.

FIRST AID MEASURES

EYE CONTACT
Wash with plenty of water for 15 minutes.
Contacter un medecin.
SKIN CONTACT
Wash with plenty of water for 15 minutes.
Consult physician if irritation develops or persists.
INHALATION
Give fresh air. Consult physician.
INGESTION
Do not induce vomiting. Drink plenty of water and contact physician.

HEALTH	**2**
FLAMMABILITY	**0**
REACTIVITY	**0**

LEGEND
0 = MINIMAL RISK
1 = SLIGHT RISK
2 = MODERATE RISK
3 = SERIOUS RISK
4 = SEVERE RISK

PERSONAL PROTECTION
Security equipment

WHMIS

IMPORTANT : Before using **WEDAC**, always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

West Penetone

MONTRÉAL
10,900 rue Sécant
Anjou, QC H1J 1S5
Tel.: 514-355-4660
Toll Free : 1 800-361-8927

EDMONTON
11411-160 Street
Edmonton, Alberta T5M 3T7
Tel.: 780-454-3919
Toll Free: 1 866-454-3919

www.westpenetone.com