ADHERE FO

Aluminum safe alkaline gel cleaner

ADHERE FO is a unique liquid alkaline product which forms a gel when diluted in water.
The gel allows the solution to adhere strongly to all surfaces to which it is applied.

ADHERE FO can be used in compressed air or aspiration foaming systems.

When used as foam with appropriate equipment, the solution clings to vertical surfaces for an almost unlimited period of time.

FEATURES AND BENEFITS

- Aluminum and soft metals safe
- Moderate caustic alkalinity
- High foaming
- Low viscosity when undiluted
- High performance product
- Extended contact time
- Economical

DIRECTION FOR USE

Use procedure	Manually remove a maximum of soil. Rinse surfaces with hot water, and apply a foam or gel solution of **ADHERE FO**. Allow to dwell, then rinse.
Concentration	Between 0.1% and 4% (1 ml to 40 ml/litre of water) according to degree of soil.
Temperature	Solution's temperature may vary between 5°C and 60°C (41 to 140°F). Note that solutions hotter than 40°C will not form a gel, they will foam.
Dwell time/Operation time	Between 5 and 20 minutes.
Mechanical action	Scrubbing or brushing recommended.
Rinsing	Rinse surfaces thoroughly with potable water.

ADHERE FO ALUMINUM SAFE ALKALINE GEL CLEANER

PHYSICAL PROPERTIES

Appearence	Clear, blue liquid
Odour	Faint detergent
Specific gravity @ 20°C	1.07
Viscosity	Not available
pH	> 13
Flash point (TCC)	None
Water solubility	Complete
Auto ignition temperature	None
Chlorine	None
Boiling point	100°C
Freezing point	Not available
Foaming tendency	High
Concentration monitoring techniques	Electrical conductivity, titration
Rinsing	Excellent

INCOMPATIBILITY

Strong acids

WAREHOUSING PRECAUTIONS

Keep containers tightly closed in a dry, cool and well-ventilated place

AVAILABLE SIZES

	20L	205L	1000L

ETIMAD HALAL

PAREVE MK 930

Food and beverage industry accepted

phosphate-FREE

IMPORTANT

Before using **ADHERE FO**, always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

FIRST AID MEASURES

Eye contact
Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician.

Skin contact
Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse.

Inhalation
Remove victim to fresh air and keep at rest in a position comfortable for breathing. Immediately call a POISON CENTER or doctor/physician.

Ingestion
Do not induce vomiting. Drink 1 or 2 glasses of water. Call a physician or Poison Control Centre immediately. Never give anything by mouth to an unconscious person.

PERSONAL PROTECTION

WHMIS

West Penetone

MONTREAL
10,900 Secant Street
Anjou, QC H1J 1S5
Tel.: 514-355-4660
Toll free : 1 800-361-8927

EDMONTON
11411-160 Street
Edmonton, Alberta T5M 3T7
Tel.: 780-454-3919
Toll free : 1 866-454-3919

www.westpenetone.com