

ACIDS



SCALEX 10 is a low-foaming, inhibited acid cleaner designed for removing various forms of mineral and mill scale from a variety of systems and units including warewash equipment, heat exchangers, steam lines, and boiler elements. The added surfactant promotes rapid surface wetting and uniform surface reaction to provide optimum scale removal without localized pitting or corrosion.

FEATURES AND BENEFITS

- Contains added corrosion inhibitor
- Low foaming
- Contains added surfactant for uniform surface wetting
- Very rapid action
- Effective on tough scale build-ups
- Rapid and uniform wetting properties prevents localized pitting and corrosion

DIRECTIONS FOR USE

Use procedure

Use **SCALEX 10** as part of a manual or low-pressure application or circulation procedure. Where applicable, scour or brush stubborn deposits. Consult with your local West Penetone sales representative for procedures best suited for your application.

Concentration

For low-pressure applications or circulation procedures, a 15% v/v dilution with water is recommended, depending on the amount of scale to be removed.

Use temperature

Effective in both hot and cold water.

Dwell time / Operation time

Allow for complete removal of scale deposits before final rinsing.

Rinsing

Cold water is recommended.

SCALEX 10

LOW-FOAMING MINERAL SCALE REMOVER

PHYSICAL PROPERTIES

Appearance	Light Green Liquid
Odour	Pungent
Specific Gravity @ 20°C	1.080-1.090
Viscosity	Thin
pH	<1.0
Flash Point (TCC)	None
Boiling Point	Approx. 100°C
Freezing Point	Approx. -15°C
Foaming Tendency	Nil
Concentration Monitoring Techniques	Not determined
Rinsability	Excellent
Water Solubility	Complete





INCOMPATIBILITY

Chlorinated, strong oxidizing or alkaline materials
Avoid prolonged contact with mild or galvanized steel

WAREHOUSING PRECAUTIONS

Keep from freezing
Keep container closed when not in use

AVAILABLE SIZES

			
4L / 1,06Gal.	20L / 5,28Gal.	205L / 54,16Gal	1000L / 264,17Gal.

FIRST AID MEASURES

EYE CONTACT

Wash with plenty of water for 15 minutes. Consult physician if irritation develops or persists.

SKIN CONTACT

Wash with plenty of water for 15 minutes. Consult physician if irritation develops or persists.

INHALATION

Give fresh air or artificial respiration. Consult physician

INGESTION

Do not induce vomiting. Drink plenty of water and consult physician immediately.

HEALTH

3

FLAMMABILITY

0

REACTIVITY

0

LEGEND

0 = MINIMAL RISK
1 = SLIGHT RISK
2 = MODERATE RISK
3 = SERIOUS RISK
4 = SEVERE RISK

PERSONAL PROTECTION Security equipment



WHMIS



IMPORTANT: Before using SCALEX 10, always be sure to read and follow precautions and directions for use appearing on the product container label and on the material safety data sheet (m.s.d.s.).

MONTREAL

10,900 rue Sécant
Anjou, QC H1J 1S5
Tel.: 514-355-4660
Toll free : 1-800-361-8927

EDMONTON

11411-160 Street
Edmonton, Alberta T5M 3T7
Tel.: 780-454-3919
Toll free: 1-866-454-3919

