

FOAM-EZE HC

HIGH-FOAMING ALKALINE CLEANER

FOAM-EZE HC is designed to clean accessible exterior surfaces in the food industry.

It is a high performance product designed for stubborn deposits such as baked or dried food, liquid smoke deposits in smoke houses and other stubborn debris.

FEATURES AND BENEFITS

- High alkalinity
- High foaming
- Compatible with chlorine
- Solvent free
- High performance product for difficult tasks
- May be used in compressed air or manual foaming systems
- The foam clings strongly to surfaces over a long period of time



DIRECTION FOR USE

| | |
|----------------------------------|---|
| Equipment to be treated | All soiled equipment found in food processing plants that are very soiled such as ham trees, smoke houses, convection ovens and other surfaces that require a highly powerful product. Animal and vegetable soil. |
| Soils to be removed | Dried or baked protein deposits, liquid smoke deposits located on the interior walls of smoke houses. |
| Use procedure | Manually remove a maximum of soil. Rinse surfaces with water. Apply FOAM-EZE HC to surfaces. Allow to dwell then rinse with water. |
| Concentration | Between 0.1% and 10% (1 ml to 100 ml / litre). |
| Temperature | Between 5°C and 60°C (41 to 140°F). |
| Dwell time/Operation time | Between 5 to 25 minutes. |
| Mechanical action | Scrubbing or brushing recommended. |
| Rinsing | Rinse well to remove all traces of product. |
| Reuse/recycling | Not possible. |

FOAM-EZE HC HIGH-FOAMING ALKALINE CLEANER

PHYSICAL PROPERTIES

| | |
|-------------------------------------|------------------------------------|
| Appearance | Clear, brown liquid |
| Odour | Faint detergent |
| Specific gravity @ 20°C | 1.20 |
| Viscosity | < 10 cps |
| pH | > 13.5 |
| Flash point (TCC) | None |
| Water solubility | Complete |
| Auto ignition temperature | None |
| Chlorine | None |
| Boiling point | 100°C |
| Freezing point | Not available |
| Foaming tendency | High |
| Concentration monitoring techniques | Electrical conductivity, titration |
| Rinsing | Excellent |

INCOMPATIBILITY

Strong acids

WAREHOUSING PRECAUTIONS

Keep containers tightly closed in a dry, cool and well-ventilated place

AVAILABLE SIZES

| | | |
|---|---|---|
|  |  |  |
| 20L | 205L | 1000L |



IMPORTANT

Before using **FOAM-EZE HC**, always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

FIRST AID MEASURES

Eye contact

Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician.

Skin contact

Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse.

Inhalation

Remove victim to fresh air and keep at rest in a position comfortable for breathing. Immediately call a POISON CENTER or doctor/physician.

Ingestion

Do not induce vomiting. Drink 1 or 2 glasses of water. Call a physician or Poison Control Centre immediately. Never give anything by mouth to an unconscious person.

PERSONAL PROTECTION



WHMIS

