

FORMULA FC-1161

HIGH FOAMING ALKALINE DEGREASER

FORMULA FC-1161 is a highly concentrated alkaline cleaner, formulated to rapidly penetrate and remove soil deposits.

FORMULA FC-1161 is intended for high pressure, foam or steam cleaning. It is recommended for the cleaning of a large variety of soils including oils, grease and tar.

FORMULA FC-1161 is particularly useful in the cleaning of heavy industrial equipment such as: mining, forest and naval equipment.

FEATURES & BENEFITS

- Powerful alkali, very efficient at low concentration
- Non corrosive to steel
- Leaves no visible streaks after rinsing
- Good penetrating properties on large deposits
- Low viscosity
- Completely soluble in water
- Phosphorus free
- Solvent free
- High foaming
- Fast acting
- Easy to rinse



DIRECTIONS FOR USE

Use procedures

Apply the solution by using low pressure or foam. Allow to dwell then rinse using high pressure. Repeat if necessary.

Concentration

Between 3% and 10%.

Temperature

Hot or cold, according to availability.

Dwell time/Operation time

Allow contact time of 5 to 10 minutes before the final rinse. If the deposits are very thick, allow to dwell for a longer period of time.

Rinsing

Rinse well in order to remove all traces of the product from the surface.

FORMULA FC-1161 HIGH FOAMING ALKALINE DEGREASER

PHYSICAL PROPERTIES

Appearance	Clear, colorless liquid
Odour	Faint detergent
Specific gravity @ 20°C	1.08
Viscosity	<10 cps
pH	>13
Flash point (TCC)	None
Water solubility	Complete
Boiling point	100°C (212°F)
Freezing point	Not available
Foaming tendency	High
Rinsing	Excellent
Concentration monitoring techniques	Electrical conductivity, refractive index, titration

INCOMPATIBILITY

Strong acids

WAREHOUSING PRECAUTIONS

Keep containers tightly closed away from direct sunlight in a dry, cool and well-ventilated place

AVAILABLE SIZES

			
20L	55L	205L	1000L



IMPORTANT

Before using **FORMULA FC-1161**, always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

FIRST AID MEASURES

Eye contact

Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician.

Skin contact

Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse.

Inhalation

Remove victim to fresh air and keep at rest in a position comfortable for breathing. Immediately call a POISON CENTER or doctor/physician.

Ingestion

Do not induce vomiting. Drink 1 or 2 glasses of water. Call a physician or Poison Control Centre immediately. Never give anything by mouth to an unconscious person.

PERSONAL PROTECTION



WHMIS

