

GRAFIKLEEN® R504 WD-ECO

ROLLER & BLANKET WASH

GRAFIKLEEN R504 WD-ECO is a state of the art roller and blanket wash.

GRAFIKLEEN R504 WD-ECO is also an excellent adhesive remover.

The solvent present in **GRAFIKLEEN R504 WD-ECO** is as effective as xylene, mineral spirits, naphtha and alcohols in the cleaning of solvent soluble inks and coatings.

FEATURES & BENEFITS

- Contains no CFCs
- Fast evaporating
- Multiple uses
- Fast cleaning
- Water extendable
- Safer for workers to use
- Mild odour
- Cost effective
- Removes glaze build-up



DIRECTIONS FOR USE

Use procedures

GRAFIKLEEN R504 WD-ECO can be used as a roller and blanket wash on most offset presses. Apply to blankets with a saturated rag or coarse spray and wipe clean. No drying or rinsing is necessary. Rollers can be cleaned by spraying **GRAFIKLEEN R504 WD-ECO** onto the rollers with an applicator bottle.

For the removal of hardened inks and adhesives, apply **GRAFIKLEEN R504 WD-ECO** by coarse spray or rag and allow to dwell for a short time. Some brushing or agitation may be necessary in areas with a heavy buildup. Remove **GRAFIKLEEN R504 WD-ECO** by wiping area with either a dry rag or mop. In some instances, a rag or mop slightly saturated with **GRAFIKLEEN R504 WD-ECO** may be beneficial.

Concentration

For rollers, 4 to 5 oz. is usually sufficient. Repeat this process until the rollers are clean.

To remove paper lint and ink in one application, dilute **GRAFIKLEEN R504 WD-ECO** 1:1 with water.

For glaze removal, dilute **GRAFIKLEEN R504 WD-ECO** with three parts water and one part solvent.

GRAFIKLEEN® R504 WD-ECO ROLLER & BLANKET WASH

PHYSICAL PROPERTIES

Appearance Clear, yellow liquid

Odour Citrus

Specific gravity @ 20°C 0.83

Viscosity <10 cps

pH Not applicable

Flash point (TCC) 40°C

Water solubility Emulsifies

Auto ignition temperature Not available

Boiling point >150°C

Freezing point Not available

Foaming tendency Not applicable

Concentration monitoring techniques Not applicable

Rinsing Not applicable

INCOMPATIBILITY

Strong oxidizing agents

WAREHOUSING PRECAUTIONS

Keep containers tightly closed in a dry, cool and well-ventilated place

AVAILABLE SIZES



205L

IMPORTANT

Before using **GRAFIKLEEN R504 WD-ECO** always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

FIRST AID MEASURES

Eye contact

Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician.

Skin contact

Wash with plenty of water. If skin irritation or rash occurs, get medical advice/attention. Take off contaminated clothing and wash it before re-use.

Inhalation

If difficulties occur after mist/vapors/spray has been inhaled, remove person to fresh air and keep comfortable for breathing. Call a POISON CENTER or doctor/physician if you feel unwell.

Ingestion

Rinse mouth. Do NOT induce vomiting. Immediately call a POISON CENTER or doctor/physician.

PERSONAL PROTECTION



WHMIS

