

ROC 55X

HIGH CAPACITY DEGASIFICATION AID & SULFIDE SCAVENGER

ROC 55X is a product used for liquid phase applications requiring the removal of high H₂S concentrations as well as for foulant removal and LEL reduction.

ROC 55X can also be used for batch fluid treatments with high H₂S demands and applied year-round for various types of cleaning applications.

FEATURES & BENEFITS

- Contains no added formaldehyde
- Kinematic viscosity data available
- Effective alternative to **ROC 40** or **ROC 45** in liquid phase applications with excessive H₂S concentrations
- Suitable for environments with temperatures as low as -49°C (-56.2°F)
- Versatile application methods



DIRECTIONS FOR USE

Use procedure

May be used with adequate high-pressure systems or by direct injection when used as part of a circulation procedure. Consult with your local West Penetone sales representative for procedures best suited for your application.

Dosage application

A minimum concentration of 5-10% v/v with water is recommended when applying by high-pressure or as part of a prescribed volume circulation/cascade procedure. When used as part of an injection procedure apply at a maximum rate of 6-8 L/min (1.5 - 2 gal./min) into a continuous water stream.

Use temperature

Ambient to a maximum of 40°C (104°F) is recommended.

Dwell time / Operation time

Dependent on job, site and method of application. 6-10 hours is recommended when accompanied by hourly gas testing and monitoring of circulation fluid.

ROC 55X HIGH CAPACITY DEGASIFICATION AID & SULFIDE SCAVENGER

PHYSICAL PROPERTIES

Appearance	Clear, yellow liquid
Odour	Alcohol/amine
Specific gravity @ 20 °C	1.015-1.025
Viscosity	Not available
pH	9.5-10.5
Flash point (TCC)	32°C (90°F)
Water solubility	Complete
Boiling point	Not available
Freezing point	-49°C (-56°F)
Foaming tendency	High
Critical micelle concentration (ppm _c)	1000
Rinsing	Excellent
Concentration monitoring techniques	Not determined

INCOMPATIBILITY

Acids, oxidizing agents

WAREHOUSING PRECAUTIONS

Keep containers tightly closed away from direct sunlight in a dry, cool and well-ventilated place

AVAILABLE SIZES

		
20L	205L	1000L

IMPORTANT

Before using **ROC 55X**, always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

FIRST AID MEASURES

Ingestion

Rinse mouth. Call a POISON CENTER or doctor/physician if you feel unwell.

Skin contact

Wash with plenty of water. Call a POISON CENTER or doctor/physician if you feel unwell. If skin irritation or rash occurs, get medical advice/attention. Take off immediately all contaminated clothing and wash it before re-use.


Inhalation

If difficulties occur after mist/vapors/spray has been inhaled, remove person to fresh air and keep comfortable for breathing. Call a POISON CENTER or doctor/physician if you feel unwell.

Eye contact

Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical advice/attention.

PERSONAL PROTECTION



WHMIS

