

RIDSTONE

FOAMING ACID CLEANER

RIDSTONE is a high foaming acid cleaner which contains mineral acids and detergents specially chosen to remove mineral deposits on surfaces.

RIDSTONE is highly effective in the removal of calcium and scale deposits found on equipment, particularly stainless steel.

RIDSTONE is also very effective in maintaining aluminum surfaces.

FEATURES & BENEFITS

- Powerful acid
- High foaming
- Foam clings to vertical surfaces
- Mild odour
- Effectively restores oxidized aluminum surfaces
- Effectively removes rust



DIRECTIONS FOR USE

Equipment to be treated	Aluminum or stainless steel surfaces.
Soils to be removed	Oxidation deposits.
Use procedure	Foam RIDSTONE solution on the surfaces to be treated.
Concentration	Between 0.1% and 8% (1 ml to 80 ml / litre), according to degree of soil.
Temperature	Warm or cold.
Dwell time/Operation time	2 to 5 minutes.
Mechanical action	Not needed for aluminum, but useful on stainless steel.
Rinsing	Rinse with cold or warm water.

RIDSTONE FOAMING ACID CLEANER

PHYSICAL PROPERTIES

Appearance	Clear, colorless liquid
Odour	Acidic
Specific gravity @ 20°C	1.17
Viscosity	<10 cps
pH	<1
Flash point (TCC)	None
Water solubility	Complete
Auto ignition temperature	None
Chlorine	None
Boiling point	100°C
Freezing point	Not available
Foaming tendency	High
Concentration monitoring techniques	Electrical conductivity, titration
Rinsing	Excellent

INCOMPATIBILITY

Bases, organic materials
light metals, bleach

WAREHOUSING PRECAUTIONS

Keep containers tightly closed in a dry,
cool and well-ventilated place

AVAILABLE SIZES

		
20L	205L	

IMPORTANT

Before using **RIDSTONE**, always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

FIRST AID MEASURES

Eye contact

Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician.

Skin contact

Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse.

Inhalation

Remove person to fresh air and keep at rest in a position comfortable for breathing. Immediately call a POISON CENTER or doctor/physician.

Ingestion

Do not induce vomiting. Drink 1 or 2 glasses of water. Call a physician or Poison Control Centre immediately. Never give anything by mouth to an unconscious person.

PERSONAL PROTECTION



WHMIS



MONTREAL

10,900 rue Secant
Anjou, QC H1J 1S5
Tel.: 514-355-4660
Toll free : 1 800-361-8927

EDMONTON

11411-160 Street
Edmonton, Alberta T5M 3T7
Tel.: 780-454-3919
Toll free : 1 866-454-3919