

WEDAC

FOAMING ACID CLEANER

WEDAC is a high foaming acid descaler. It is designed to remove scale on food and beverage processing equipment.

WEDAC can be applied to surfaces where cleaning by circulation is impossible.

WEDAC is also effective on oxidized aluminum to restore its shine.

FEATURES & BENEFITS

- High foaming
- Water dilutable
- Mild odour
- Easy to apply with automatic foaming equipment.
- Its foam clings to surfaces allowing a longer contact time even at low concentration
- Heavy duty



DIRECTIONS FOR USE

Equipment to be treated	Stainless steel, aluminum or plastic surfaces.
Soils to be removed	Mineral deposit, limestone, magnesium, iron and rust.
Use procedure	Apply manually or with appropriate foaming equipment.
Concentration	0.1% to 10% (1 to 100 ml/l) according to degree of soil.
Use temperature	Between 10°C and 60°C (50 to 140°F).
Dwell time/Operation time	Between 3 and 25 minutes.
Mechanical action	Scrubbing recommended.
Rinsing	Rinse with potable water.

PHYSICAL PROPERTIES

Appearance	Clear, red liquid
Odour	Faint detergent
Specific gravity @ 20°C	1.4
Viscosity	10 - 30 cps
pH	< 1
Flash point (TCC)	None
Water solubility	Complete
Auto ignition temperature	None
Chlorine	None
Boiling point	100°C
Freezing point	Not available
Foaming tendency	high
Concentration monitoring techniques	Titration
Rinsing	Excellent

INCOMPATIBILITY

Bases, organic materials, light metals, bleach

WAREHOUSING PRECAUTIONS

Keep containers tightly closed in a dry, cool and well-ventilated place

AVAILABLE SIZES

			
4 X 4L	20L	205L	1000L



IMPORTANT

Before using **WEDAC**, always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

FIRST AID MEASURES

Eye contact

Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician.

Skin contact

Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse.

Inhalation

Remove victim to fresh air and keep at rest in a position comfortable for breathing. Immediately call a POISON CENTER or doctor/physician.

Ingestion

Do not induce vomiting. Drink 1 or 2 glasses of water. Call a physician or Poison Control Centre immediately. Never give anything by mouth to an unconscious person.

PERSONAL PROTECTION



WHMIS

