

WESTSURF 10

SURFACTANT DEGREASER CONCENTRATE

WESTSURF 10 is a non-diluted surfactant concentrate designed to increase or improve wetting and detergency of blends, hot water flushes or steam applied in vessel decontamination procedures.

WESTSURF 10 will assist in remediating LEL and H₂S gas contamination.

FEATURES & BENEFITS

- High foaming liquid
- Moderate viscosity
- No added water
- Neutral pH
- Easily diluted to desired concentration
- Non-diluted, surfactant concentrated formula provides optimum wetting and foulant removal



DIRECTIONS FOR USE

Area of application

Interior of pipes, tanks or vessels requiring foulant removal and full decontamination.

Use procedure

Use **WESTSURF 10** as part of a circulation or vapor phase procedure. May be used at concentrate when applied manually or diluted on-site up to 2-5% v/v when part of a chemical blend procedure. When used as part of a water flush or steam injection, consult your West Penetone sales representative for further information.

Use temperature

60-80°C (140-176°F) is recommended.

Dwell time / Operation time

Dependent on job, site and method of application. Consult your West Penetone sales representative for further information.

IMPORTANT

When diluted in concentrated acid or alkali, mix well and use immediately for best results.

WESTSURF 10 SURFACTANT DEGREASER CONCENTRATE

PHYSICAL PROPERTIES

Appearance	Clear, colorless liquid
Odour	Glycol
Specific gravity @ 20 °C	0.975-0.980
Viscosity	Not available
pH	7.0-8.0
Flash point (TCC)	None
Water solubility	Complete
Freezing point	Approx. 0°C (32°F)
Boiling point	Approx. 100°C (212°F)
Foaming tendency	High
Rinsing	Excellent

INCOMPATIBILITY

Acids, strong oxidizing agents

WAREHOUSING PRECAUTIONS

Keep containers tightly closed away from direct sunlight in a dry, cool and well-ventilated place

AVAILABLE SIZES

			
	20L	205L	1000L

IMPORTANT

Before using **WESTSURF 10**, always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

FIRST AID MEASURES

Ingestion

Rinse mouth. Remove person to fresh air and keep at rest in a position comfortable for breathing. Do not induce vomiting unless directed by medical personnel. Call a POISON CENTER or doctor/physician if you feel concerned or unwell.

Skin contact

Wash with plenty of water. If skin irritation occurs, get medical advice/attention. Take off contaminated clothing and wash it before re-use.

Inhalation

If difficulties occur after mist/spray has been inhaled, remove person to fresh air and keep comfortable for breathing. Call a POISON CENTER or doctor/physician if you feel unwell.

Eye contact

Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician.

PERSONAL PROTECTION



WHMIS

