

PINKROC

HEAVY-DUTY DETERGENT & DECONTAMINATION ADDITIVE

PINKROC is a heavy-duty detergent and decontamination additive designed for vessel cleaning applications requiring the removal of oils and grease and the remediation of LEL gas contamination. A high surfactant concentration provides fast wetting and emulsification to impart clean surfaces, rapid oily soil mobilization, and a gas-free environment.

PINKROC is also a variable use product appropriate for use in manual cleaning applications.

FEATURES & BENEFITS

- High foaming liquid
- High viscosity
- Pleasant bubble-gum fragrance
- Non-flammable
- Variable-use product formulation
- No added solvents or harsh alkali ingredients
- Rapidly diluted to desired concentration
- Will assist in remediating LEL gas contamination for vessel decontamination procedures
- Compatible with all metallurgy
- Coloration provides visual confirmation of solution strength



DIRECTIONS FOR USE

Use procedure

Use **PINKROC** as part of a static soak or liquid circulation step in a vessel decontamination procedural plan. Consult with your local West Penetone Inc. sales representative for procedures best suited for your application

Dosage application

Dilute 1-10% v/v with water, depending on type and amount of soils and LEL gases present for all applications.

Use temperature

40-60°C is recommended for all vessel decontamination procedures.

Use at ambient temperature for manual cleaning applications.

Dwell time / Operation time

Dependent on job, site, and method of application. Retain monitoring is recommended. Consult your sales representative for further information.

Rinsing

High-pressure or high-volume water circulation is recommended.

PINKROC HEAVY-DUTY DETERGENT & DECONTAMINATION ADDITIVE

PHYSICAL PROPERTIES

Appearance	Clear, red liquid
Odour	Bubble-gum
Specific gravity @ 20 °C	1.035-1.045
Viscosity	Not available
pH	9.0-10.0
Flash point (TCC- COC)	None
Water solubility	Complete
Boiling point	Approx. 100°C (212°F)
Freezing point	Approx. 0°C (32°F)
Foaming tendency	High
Rinsing	Excellent
Concentration monitoring techniques	Visual

INCOMPATIBILITY

Acids, bases, strong oxidizing agents

WAREHOUSING PRECAUTIONS

Keep containers tightly closed away from direct sunlight in a dry, cool and well-ventilated place

AVAILABLE SIZES

		
20L	205L	1000L

IMPORTANT

Before using **PINKROC**, always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

FIRST AID MEASURES

Ingestion

Do NOT induce vomiting. Aspiration of material due to vomiting can cause chemical pneumonitis. If vomiting occurs naturally, the casualty should lean forward to reduce risk of aspiration. Rinse mouth. Call a POISON CENTER or doctor/physician if you feel unwell.

Skin contact

Take off immediately all contaminated clothing. Rinse skin with water or shower. Wash contaminated clothing before reuse.

Inhalation

Remove person to fresh air and keep comfortable for breathing. Immediately call a POISON CENTER or doctor/physician.

Eye contact

Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician

PERSONAL PROTECTION



WHMIS



MONTREAL

10,900 rue Secant
Anjou, QC H1J 1S5
Tel.: 514-355-4660
Toll free : 1 800-361-8927

EDMONTON

11411-160 Street
Edmonton, Alberta T5M 3T7
Tel.: 780-454-3919
Toll free : 1 866-454-3919