

## AccuTerge Tech 70

### PRESSURE WASHER LIQUID

**AccuTerge Tech 70** is a premium liquid pressure-washer detergent designed to remove the most stubborn road film, bug stains, road salts, and windshield eyebrows. **AccuTerge Tech 70** is a specially balanced formulation that works in heavy-duty truck wash applications but is also safe for use on the finest automobile finishes.

**AccuTerge Tech 70** is effective as a presoak, detergent, and foamer in touchless and wand wash carwash applications. **AccuTerge Tech 70** is a high foaming and easy rinsing product that is safe for all types of pressure washers. It works well in both hard and soft water areas and is suitable for use in recycled water systems. Carwash operators that have installed water-softening equipment will achieve excellent performance at lower product concentrations.

### FEATURES & BENEFITS

- Excellent on road film, bugs, windshield eyebrows, and road salts
- Highly active formula
- High foaming and easy rinsing product
- Safe for all types of pressure washers
- Phosphate free
- Suitable for any car wash that uses foamers, wands, and touchless applications



### DIRECTIONS FOR USE

<b>Use procedure</b>	Use <b>AccuTerge Tech 70</b> as a presoak, detergent, and foaming soap in touchless and wand wash carwash applications in either soft or hard water environments.
<b>Concentration</b>	60:1 to 100:1 touchless presoak or foamer applications Up to 400:1 for all other applications
<b>Use temperature</b>	Can be used in both hot and cold-water cleaning applications. For best results, hot water (50°C – 60°C / 120°F – 140°F) and wand pressure of 1000 to 1200 PSI are recommended.
<b>Rinsing</b>	High pressure hot water is recommended.

# ACCUTERGE TECH 70 PRESSURE WASHER LIQUID

## PHYSICAL PROPERTIES

Appearance	Clear, red liquid
Odour	Mild detergent
Specific gravity @ 20°C	1.109-1.129
Viscosity	Not available
pH	12.0 – 13.0 (10% v/v solution in water)
Flash point (TCC)	None
Water solubility	Complete
Boiling point	Approx. 100°C (212°F)
Freezing point	Approx. 0°C (32°F)
Foaming tendency	High
Rinsing	Excellent
Concentration monitoring techniques	Electrical conductivity, titration

## INCOMPATIBILITY

Strong oxidizing agents, acids

## WAREHOUSING PRECAUTIONS

Store away from incompatible materials  
Keep from freezing

## AVAILABLE SIZES

			
20L	115L	205L	1040L



## IMPORTANT

Before using **ACCUTERGE TECH 70** always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

## FIRST AID MEASURES

### Ingestion

Do not induce vomiting unless directed by medical personnel. Rinse mouth with water and drink 1 or 2 glasses of water and call a POISON CENTER or doctor/physician immediately.

### Skin contact

Take off contaminated clothing and rinse skin with plenty of water. Get medical advice/attention. Wash any contaminated clothing before re-use.

### Inhalation

If difficulties occur after mist/vapors/spray has been inhaled, remove person to fresh air and keep comfortable for breathing. Call a POISON CENTER or doctor/physician.

### Eye contact

Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Call a doctor/physician immediately.

## PERSONAL PROTECTION



WHMIS

