

AccuTREAT 720

BOILER WATER CORROSION AND SCALE CONTROL ADDITIVE

AccuTREAT 720 is a corrosion control and scale inhibiting treatment for industrial steam boilers.

AccuTREAT 720 is formulated with scale inhibitors, dispersants, corrosion inhibitors and alkalinity regulators. These chemicals work together to control corrosion and prevent the deposition of solids on metal surfaces of the boiler, even under severe operating conditions.

FEATURES AND BENEFITS

- Multiple lines of defense against scaling and corrosion
- Contains chelators, sequestrants and polymeric dispersants to minimize control of solids on boiler surfaces
- Maintains boiler alkalinity at optimum range to prevent corrosion and reduce boiler carryover



DIRECTION FOR USE

Use procedure

AccuTREAT 720 should be dosed into the boiler feedwater, using a chemical metering pump, at a rate that ensures a residual orthophosphate level of 30 to 60 ppm in the boiler. The precise dosage for each individual system will depend on the feedwater hardness and the amount condensate return.

AccuTREAT 720 may be pre-diluted with water before injection into the feed water, using a chemical metering pump.

ACCUTREAT 720 BOILER WATER CORROSION AND SCALE CONTROL ADDITIVE

PHYSICAL PROPERTIES

Appearance	Clear, colorless liquid
Odour	Odorless
Specific gravity @ 20°C	1.108-1.128
Viscosity	Not available
pH	12.0 – 13.0 (10% v/v solution in water)
Flash point (TCC)	None
Water solubility	Complete
Boiling point	Approx. 100°C (212°F)
Freezing point	< 0°C (32°F)
Foaming tendency	Non-foaming
Concentration monitoring techniques	Boiler test kit
Rinsing	Not applicable

INCOMPATIBILITY

Aluminum, tin, zinc, magnesium and other soft metals/alloys, strong oxidizing agents, acids

WAREHOUSING PRECAUTIONS

Store away from incompatible materials
Keep from freezing

AVAILABLE SIZES

			
20L	205L		

IMPORTANT

Before using **ACCUTREAT 720** always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

FIRST AID MEASURES

Eye contact

Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Call a POISON CENTER or doctor/physician immediately.

Skin contact

Take off contaminated clothing and rinse skin with plenty of water. Get medical advice/attention. Wash any contaminated clothing before re-use.

Inhalation

If difficulties occur after mist/vapors/spray has been inhaled, remove person to fresh air and keep comfortable for breathing. Call a POISON CENTER or doctor/physician.

Ingestion

Do not induce vomiting unless directed by medical personnel. Rinse mouth with water and drink 1 or 2 glasses of water and call a POISON CENTER or doctor/physician immediately.

PERSONAL PROTECTION



WHMIS

