

BERRY SHINE

VEHICLE SPRAYWAX

BERRY SHINE is a concentrated spray wax drying aid with a delightful berry scent. It imparts rapid beading and sheeting action to the vehicle surface to ensure water drains swiftly, thus expediting the drying process.

BERRY SHINE enhances the customer experience by infusing a pleasant berry scent while imparting a lustrous sheen to the car's finish during the final step of the carwash.

The **BERRY SHINE** micro-emulsion is stable over long periods of storage, eliminating any worries about partial separation in either diluted or concentrated form.

FEATURES & BENEFITS

- Highly concentrated formula
- Cost effective- excellent performance at high dilution
- Promotes rapid water beading to minimize drying time
- Pleasant berry fragrance
- Stable micro-emulsion ensures consistent and reliable performance



DIRECTIONS FOR USE

- | | |
|------------------------|---|
| Use procedure | Apply diluted BERRY SHINE solution to vehicle surface immediately after the last high-pressure rinse. Ensure even coverage of all surfaces Allow dwell time of 20 – 30 seconds for wax to adhere then rinse thoroughly with deionized water to ensure a spot-free surface. |
| Concentration | 500:1 to 1000:1 for touchless or wand wash applications |
| Use temperature | Can be used in both hot and cold-water cleaning applications. |
| Rinsing | Rinse with low pressure spray of deionized (reverse osmosis) water. |

BERRY SHINE VEHICLE SPRAYWAX

PHYSICAL PROPERTIES

Appearance	Clear, yellow liquid
Odour	Berry
Specific gravity @ 20°C	0.980 – 1.000
Viscosity	Not available
pH	6.5 – 7.5 (10 % v/v solution in water)
Flash point (TCC)	Not applicable
Water solubility	Not soluble
Boiling point	Approx. 100°C (212°F)
Freezing point	Not available
Foaming tendency	Emulsifies
Rinsing	Good
Concentration monitoring techniques	Not determined

INCOMPATIBILITY

Strong oxidizing agents

WAREHOUSING PRECAUTIONS

Keep in a dry, cool, and well-ventilated place, away from incompatible materials

AVAILABLE SIZES

			
20L	115L	1000L	

IMPORTANT

Before using **BERRY SHINE** always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

FIRST AID MEASURES

Ingestion

Rinse mouth. Do NOT induce vomiting. Drink one or two glasses of water or milk. Call a POISON CENTER or doctor/physician if you feel unwell.

Skin contact

Wash with plenty of water. If skin irritation occurs, get medical advice/attention. Take off contaminated clothing and wash before reuse.

Inhalation

If difficulties occur after mist/vapors/spray has been inhaled, remove person to fresh air and keep comfortable for breathing. Call a POISON CENTER or doctor/physician if you feel unwell.

Eye contact

Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Get medical advice/attention immediately.

PERSONAL PROTECTION



WHMIS

