

FOAM-EZE HC

HIGH-FOAMING ALKALINE CLEANER

FOOD INDUSTRY



Food and beverage industry accepted

FOAM-EZE HC is designed to clean accessible exterior surfaces in the food industry. It is a high performance product designed for stubborn deposits such as baked or dried food, liquid smoke deposits in smoke houses and other stubborn debris

FEATURES and BENEFITS

- · High alkalinity
- · High foaming
- Compatible with chlorine
- Solvent free
- · High performance product for difficult tasks
- · May be used in compressed air or manual foaming systems
- The foam clings strongly to surfaces over a long period of time





DIRECTION FOR USE

Approved for organic agriculture by OCQV

Equipment to be treated

All soiled equipment found in food processing plants that are very soiled such as ham trees, smoke houses, convection ovens and other surfaces that require a highly powerful product. Animal and vegetable soil.

Soils to be removed

Dried or baked protein deposits, liquid smoke deposits located on the interior walls of smoke houses.

Use procedure

Remove a maximum of soil by hand scraped. Rinse surfaces with hot water. Apply **FOAM-EZE HC** to surfaces. Allow to dwell then rinse with water.

Concentration

Between 0.1% and 10% (1 ml to 100 ml / litre)

Temperature

Between 5°C and 60°C (41°F to 140°F)

Dwell time/Operation time

Between 5 to 25 minutes.

Mechanical action

Scrubbing or brushing recommended.

Rinsing

Rinse well to remove all traces of product.

Reuse/recycling

Not possible

FOAM-EZE HC

HIGH-FOAMING ALKALINE CLEANER

PHYSICAL PROPERTIES

Appearance	Clear dark brown liquid
Odour	Mild
Specific gravity @ 20°C	1.20
Viscosity	Low
рН	13.5
Flash point (TCC)	None
Phosphorus	None
Water solubility	Complete
Auto ignition temperature	None
Chlorine	No
Boiling point	100°C
Freezing point	<-5°C
Foaming tendency	High
Concentration monitoring techniques	Conductivity, titration
Rinsing	Excellent

INCOMPATIBILITY

Aluminium and other soft metals Galvanized steel

WAREHOUSING PRECAUTIONS

Avoid freezing

FIRST AID MEASURES

EYE CONTACT

Wash with plenty of water for 15 minutes. Consult physician.

SKIN CONTACT

Wash with plenty of water for 15 minutes. Consult physician if irritation develops or persists.

INHALATION

Give fresh air

INGESTION

Do not induce vomiting. Drink plenty of water and contact physician.

HEALTH	3
FLAMMABILITY	0
REACTIVITY	0

LEGEND

- 0 = MINIMAL RISK
- 1 = SLIGHT RISK
- 2 = MODERATE RISK
- 3 = SERIOUS RISK
- 4 = SEVERE RISK

PERSONAL PROTECTION Security equipment

WHMIS 🐷

IMPORTANT: Before using **FOAM-EZE HC**, always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).



MONTRÉAL

10,900 rue Sécant Anjou, QC H1J 1S5 Tel.: 514-355-4660 Toll Free : 1 800-361-8927

EDMONTON

11411-160 Street Edmonton, Alberta T5M 3T7 Tel.: 780-454-3919 Toll Free: 1 866-454-3919

www.westpenetone.com