

FORMULA FC-1160

ALKALINE DEGREASER

FORMULA FC-1160 is a liquid alkaline cleaner specially designed for heavy duty applications.

FORMULA FC-1160 can be used with high or low pressure cleaning in heavy industry such as: mines, paper mills, flexographic printing industries, forest equipment, trucks, trains, naval machinery, etc.

FEATURES & BENEFITS

- Moderate foam
- No flash or fire point
- Completely water soluble
- Very effective
- Cost efficient since it is dilutable
- Easy to rinse and does not leave any streaks
- Fast acting



DIRECTIONS FOR USE

Use procedures

If the deposits are extremely thick, remove as much as possible with a brush or scraper. Apply a solution of **FORMULA FC-1160**. Allow to dwell 5 to 15 minutes. Scrub or brush if necessary. Rinse with high-pressure hot water if available. If not, use low pressure.

Concentration

Between 5% and 20% is generally recommended.

Dwell time/Operation time

5 to 15 minutes.

Rinsing

Hot water is recommended.

FORMULA FC-1160

ALKALINE DEGREASER

PHYSICAL PROPERTIES

Appearance	Clear, colorless liquid
Odour	Faint detergent
Specific gravity @ 20°C	1.08
Viscosity	<10 cps
pH	13
Flash point (TCC)	None
Water solubility	Complete
Boiling point	100°C (212°F)
Freezing point	Not available
Foaming tendency	Moderate
Rinsing	Excellent
Concentration monitoring techniques	Electrical conductivity, titration

INCOMPATIBILITY

Strong acids

WAREHOUSING PRECAUTIONS

Keep containers tightly closed away from direct sunlight in a dry, cool and well-ventilated place

AVAILABLE SIZES

			
	20L	205L	1000L

IMPORTANT

Before using **FORMULA FC-1160**, always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

FIRST AID MEASURES

Eye contact

Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician.

Skin contact

Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse.

Inhalation

Remove person to fresh air and keep at rest in a position comfortable for breathing. Immediately call a POISON CENTER or doctor/physician.

Ingestion

Do not induce vomiting. Drink 1 or 2 glasses of water. Call a physician or Poison Control Centre immediately. Never give anything by mouth to an unconscious person.

PERSONAL PROTECTION



WHMIS

