

LEMON LITE INDUSTRIAL

HEAVY-DUTY DETERGENT & DEGREASER ADDITIVE

LEMON LITE INDUSTRIAL is a heavy duty detergent and degreaser additive designed for general cleaning applications requiring the removal of oils and grease from parts and equipment. It also effectively remediates low LEL gas contamination when used as an additive in vessel decontamination procedures using **ROC 55X** or **ROC 60VP**.

Conversely, its high surfactant content can be utilized to impart surface lubrication to various pumps and parts in a variety of applications.

FEATURES & BENEFITS

- High foaming liquid
- High viscosity
- Near-neutral pH
- Pleasant lemon fragrance
- Non-flammable
- No VOC's
- Easily diluted to desired concentration
- Will assist in remediating LEL gas contamination for vessel decontamination procedures
- Compatible with all metallurgy



DIRECTIONS FOR USE

Use procedure	Use LEMON LITE INDUSTRIAL as part of a manual cleaning or spray procedure or as an additive in steam or high-pressure decontamination procedures.
Concentration	For manual applications, dilute 1-10% v/v with water, depending on type and amount of soils present. As an additive for decontamination procedures, use at a 2-5% v/v concentration.
Use temperature	Ambiant when used manually. 40-60°C (104-140°F) is recommended for steam or high-pressure decontamination procedures.
Dwell time / Operation time	Dependent on job, site and method of application. Consult your West Penetone sales representative for further information.
Rinsing	High-pressure, hot water is recommended.

LEMON LITE INDUSTRIAL HEAVY-DUTY DETERGENT & DEGREASER ADDITIVE

PHYSICAL PROPERTIES

Appearance	Clear, yellow liquid
Odour	Lemon
Specific gravity @ 20 °C	1.020-1.040
Viscosity	Not available
pH	8.3-9.5
Flash point (TCC)	None
Water solubility	Complete
Freezing point	Approx. 0°C (32°F)
Boiling point	Approx. 100°C (212°F)
Foaming tendency	High
Rinsing	Excellent

INCOMPATIBILITY

Acids, bases, strong oxidizing agents

WAREHOUSING PRECAUTIONS

Keep containers tightly closed away from direct sunlight in a dry, cool and well-ventilated place

AVAILABLE SIZES

		
20L	205L	1000L

IMPORTANT

Before using **LEMON LITE INDUSTRIAL**, always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

FIRST AID MEASURES

Ingestion

Rinse mouth. Do NOT induce vomiting. Call a POISON CENTER or doctor/physician if you feel unwell.

Skin contact

Rinse skin with plenty of water. If skin irritation or rash occurs, get medical advice/attention. Wash contaminated clothing before re-use.

Inhalation

Remove person to fresh air and keep comfortable for breathing. Call a POISON CENTER or doctor/physician if you feel unwell.

Eye contact

Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists, get medical advice/attention.

PERSONAL PROTECTION



WHMIS

