

SAFETY DATA SHEET

PENETONE 4015P Page 1 of 6

PENETONE 4015P SDS GHS

1. IDENTIFICATION

Product Identifier

Product Name
PENETONE 4015P
Chemical Name
Paraffin solvent

Recommended use of the chemical and restrictions on use

Recommended use Paraffin solvent
Restrictions on use Paraffin solvent
No information available

<u>Supplier details</u> West Penetone Inc.

11411-160 Street Edmonton, AB, T5M3T7

Tel: 780-454-3919

Emergency Telephone Number

Main office - (780)-454-3919, 8:00 AM to 4:30 PM MST

2. HAZARDS IDENTIFICATION

Classification

Flammable liquids	Category 2
Acute toxicity, inhalation - gases	Category 4
Skin corrosion/irritation	Category 2
Serious eye damage/eye irritation	Category 2B
Reproductive toxicity	Category 2
Specific target organ toxicity – single exposure	Category 3
Specific target organ toxicity – repeated exposure	Category 2
Aspiration hazard	Category 1
Hazardous to the aquatic environment, acute hazard	Category 2
Hazardous to the aquatic environment, long-term hazard	Category 2

Label Elements

DANGER

Hazard Statements

Highly flammable liquid and vapor

Harmful if inhaled

Causes skin irritation

Causes eye irritation

Suspected of damaging fertility or the unborn child

May cause drowsiness or dizziness

May cause damage to organs through prolonged or repeated exposure

May be fatal if swallowed and enters airways

Toxic to aquatic life

Toxic to aquatic life with long lasting effects









Precautionary Statements - Prevention

Obtain special instructions before use.

Do not handle until all safety precautions have been read and understood.

PENETONE 4015P Page 2 of 6

PENETONE 4015P SDS GHS

Keep away from heat/sparks/open flames/hot surfaces. No smoking.

Keep container tightly closed.

Avoid breathing fume/gas/mist/vapors/spray.

Wash face, hands and any exposed skin thoroughly after handling.

Use only outdoors or in a well-ventilated area.

Avoid release to the environment.

Wear protective gloves/protective clothing/eye protection/face protection.

Precautionary Statements - Response

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: get medical advice/attention.

IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water or shower. If skin irritation occurs: get medical advice/attention. Wash contaminated clothing before reuse.

IF INHALED: Remove person to fresh air and keep comfortable for breathing. Call a POISON CENTER or doctor/physician if you feel unwell.

IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. Immediately call a POISON CENTER or doctor/physician.

If exposed or concerned: Get medical advice/attention if you feel unwell.

Collect spillage.

In case of fire: Use carbon dioxide, foam or dry chemical to extinguish.

Precautionary Statements - Storage

Store locked up. Store in a well ventilated place. Keep container tightly closed. Keep cool.

Precautionary Statements - Disposal

Dispose of contents/container to an approved waste disposal plant according to local, provincial/federal regulations.

3. COMPOSITION / INFORMATION ON INGREDIENTS

Chemical Name	CAS-No	Weight %*
toluene	108-88-3	30-60
n-hexane	110-54-3	15-40
n-heptane	142-82-5	10-30

^{*} The actual concentrations have been withheld as a trade secret

4. FIRST AID MEASURES

Eye contact Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do.

Continue rinsing. If eye irritation persists: get medical advice/attention.

Skin contact Wash with plenty of water. If skin irritation occurs, get medical advice/attention. Take off contaminated

clothing and wash before reuse.

Inhalation If difficulties occur after fume/gas/mist/vapors/spray has been inhaled, remove person to fresh air and

keep comfortable for breathing. Call a POISON CENTER or doctor/physician if you feel unwell.

Ingestion Rinse mouth. Do NOT induce vomiting. Immediately call a POISON CENTER or doctor/physician.

Most important symptoms and effects, both acute and delayed

Contact with eyes may cause irritation, discomfort or pain, excess blinking and tear production with marked redness of the conjunctiva. Contact with skin may be harmful if absorbed and cause irritation with local redness. Inhalation of fume/gas/mist/vapors/spray may cause respiratory tract irritation. Inhalation of vapors may cause drowsiness or dizziness, headaches, fatigue, muscular weakness and in extreme cases, loss of consciousness. Ingestion may be harmful and cause gastrointestinal irritation, nausea, vomiting and diarrhea. Ingestion may cause pneumonitis if aspirated. Material contains ingredients which may cause damage to the nervous system (CNS), brain, peripheral nervous system (PNS), heart, liver, kidneys, lungs, bladder, eyes or testes through prolonged or repeated exposure. See Section 2 for possible delayed effects.

Indication of any immediate medical attention and special treatment needed

Treat symptomatically.

5. FIRE-FIGHTING MEASURES

Suitable Extinguishing Media

Use extinguishing measures that are appropriate to local circumstances and the surrounding environment.

PENETONE 4015P Page 3 of 6

PENETONE 4015P SDS GHS

Unsuitable Extinguishing Media

High-volume water jet.

Specific hazards arising from the chemical

During fire, gases hazardous to health may be formed including oxides of carbon.

Protective Equipment and Precautions for Firefighters

As in any fire, wear self-contained breathing apparatus pressure-demand, MSHA/NIOSH (approved or equivalent) and full protective gear.

6. ACCIDENTAL RELEASE MEASURES

Personal precautions, protective equipment and emergency procedures

Ensure adequate ventilation. Avoid breathing fume/gas/mist/vapors/spray. Put on personal protective equipment. Remove all sources of ignition. Evacuate personnel to safe areas. Beware of vapors accumulating to form explosive concentrations. Vapors can accumulate in low areas.

Environmental Precautions

Avoid discharge into drains/surface waters/groundwater.

Methods and material for containment and cleaning up

Contain and solidify with inert absorbent material. Keep in suitable, closed containers for disposal. Following product recovery, flush contaminated area with water. For large spills, stop flow of material, prevent product from entering drains, and pump off product where this is without risk and possible. Proceed as above.

7. HANDLING AND STORAGE

Precautions for Safe Handling

Handling Avoid inhalation of fume/gas/mist/vapors/spray. Avoid contact with skin, eyes and clothing. Ensure

thorough ventilation of work areas. Use personal protective equipment. Use explosion-proof equipment. Keep away from sources of ignition. Smoking should be prohibited in the application

area.

Conditions for safe storage, including any incompatibilities

Storage Keep containers tightly closed away from direct sunlight in a dry, cool and well-ventilated place,

away from incompatible materials.

Incompatible Materials Acids, oxidizing agents

8. EXPOSURE CONTROLS / PERSONAL PROTECTION

Control parameters

Only constituents with exposure limits are listed. Any constituent not listed has no known exposure limit.

Chemical Name	ACGIH TLV	OSHA PEL	NIOSH IDLH
toluene 108-88-3	TWA: 20 ppm	TWA: 100 ppm/375 mg/m ³ STEL: 150 ppm/560 mg/m ³	Not listed
n-hexane 110-54-3	TWA: 20 ppm/72 mg/m ³	TWA: 50 ppm/180 mg/m ³ STEL: 400 ppm/1440 mg/m ³	Not listed
n-heptane 142-82-5	TWA: 400 ppm STEL: 500 ppm	TWA: 400 ppm/1600 mg/m ³ STEL: 500 ppm/2000 mg/m ³	Not listed

Appropriate engineering controls

Engineering Controls Ensure adequate ventilation, especially in confined areas.

Individual protection measures, such as personal protective equipment

Eye/face Protection Safety glasses with side shields or goggles. Use a face-shield where mode of handling increases risk

of splashing.

PENETONE 4015P Page 4 of 6

PENETONE 4015P SDS GHS

Skin and body protection Wear protective gloves and protective clothing.

Respiratory Protection Wear respiratory protection if ventilation is inadequate. Use respiratory protection in case of

vapor/aerosol release.

Handle in accordance with good industrial hygiene and safety practice. Routinely wash work clothing **General Hygiene Considerations**

and protective equipment to remove contaminants.

9. PHYSICAL AND CHEMICAL PROPERTIES

APPEARANCE: VAPOR PRESSURE, mm Hg AT 20°C:

Clear, colorless liquid Not available

ODOR **VAPOR DENSITY (Air = 1):**

Solvent

ODOR THRESHOLD: RELATIVE DENSITY AT 20°C:

Not available 0.750-0.800

SOLUBILITY IN WATER: pH: Insoluble

Not applicable

MELTING POINT / FREEZING POINT: PARTITION COEFFICIENT, N-OCTANOL/WATER:

Not available

BOILING POINT/BOILING RANGE: AUTO-IGNITION TEMPERATURE:

Not available

DECOMPOSITION TEMPERATURE: FLASH POINT: <5°C (TCC)

Not available VISCOSITY: Not available

FLAMMABILITY (SOLID, GAS): FLAMMABLE LIMITS:

Not applicable **UPPER:** 1% v/v LOWER: 7% v/v

10. STABILITY AND REACTIVITY

Reactivity

Not reactive.

Not available

Chemical Stability

Stable under normal conditions.

Possibility of hazardous reactions

EVAPORATION RATE, water = 1:

Under normal conditions of storage and use, hazardous reactions will not occur.

Conditions to Avoid

Avoid extreme temperatures. Store away from incompatible materials.

Incompatible Materials

Strong oxidizing materials, acids.

Hazardous decomposition products

Under normal conditions of storage and use, hazardous decomposition products should not be produced. Thermal decomposition can lead to release of irritating gases and vapors such as oxides of carbon as well as other low molecular weight hydrocarbons.

11. TOXICOLOGICAL INFORMATION

Acute toxicity

Chemical Name	LD50 Oral	LD50 Dermal	LC50 Inhalation
toluene 108-88-3	5580 mg/kg (rat)	12160 mg/kg (rabbit)	7585 ppm (rat) – 4h dust/mist 12500 – 28800 mg/m³ (rat) – 4h
n-hexane 110-54-3	16 - 25 g/kg (rat)	3350 mg/kg (rabbit)	48000 – 73680 ppm (rat) – 4h 259354 mg/m³ (rat) – 4h
n-heptane 142-82-5	>5000 mg/kg (rat)	>2000 mg/kg (rabbit)	48000 ppm (rat) – 4h 103000 mg/m³ (rat) – 4h

Information on likely sources of exposure

Inhalation May cause respiratory irritation drowsiness or dizziness.

Serious eye damage/irritation Causes eye irritation. May cause pain, watering, redness, and blurred vision. **PENETONE 4015P** Page 5 of 6

PENETONE 4015P SDS GHS

Skin corrosion/irritation

Causes skin irritation possible dermatitis with prolonged exposure.

Ingestion

May be harmful if swallowed. May cause stomach pains and other delayed effects.

Delayed and immediate effects and also chronic effects from short and long-term exposure

Respiratory or skin sensitization Not a sensitizer. Germ cell mutagenicity None known

Carcinogenicity None known.

Reproductive toxicity toluene (CAS 108-88-3) 2 Suspected of damaging fertility or the unborn child n-hexane (CAS110-54-3 2 Suspected of damaging fertility or the unborn child

toluene (CAS 108-88-3) 3 May cause drowsiness or dizziness STOT - single exposure n-hexane (CAS110-54-3 3 May cause drowsiness or dizziness

n-heptane (CAS 142-82-5) 3 May cause drowsiness or dizziness

STOT - repeated exposure toluene (CAS 108-88-3) 2 May damage bladder, liver, kidney, brain by skin absorption

n-hexane (CAS110-54-3 2 May damage peripheral nervous system, kidney, testes by skin absorption

Aspiration Hazard toluene (CAS 108-88-3) 1 May be fatal if swallowed and enters airways n-hexane (CAS110-54-3 1 May be fatal if swallowed and enters airways

n-heptane (CAS 142-82-5) 1 May be fatal if swallowed and enters airways

Symptoms related to the physical, chemical and toxicological characteristics

See Section 2 & 4.

12. ECOLOGICAL INFORMATION

Ecotoxicity

If available, ecotoxicity values of individual components are shown below.

Chemical Name	Fish	Waterflea	Algae
toluene 108-88-3	7.63 mg/L: 96 h rainbow trout LC50	6 mg/L: 48 h daphnia magna EC50	>100 mg/L: 96 h EL50
n-hexane	12.51 mg/L: 96 h rainbow trout	21.85 mg/L: 48 h daphnia magna	12.51 mg/L: 96 h LL50
110-54-3	LL50	EL50	
n-heptane	1.284 mg/L: 96 h rainbow trout	1.5 mg/L: 48 h daphnia magna	4.338 mg/L: 72 h pseuodkirchneriella subcapitata EL50
142-82-5	LL50	EC50	

Persistence and degradability

Expected to be readily biodegradable.

Bioaccumulative potential

Indication of accumulation in organisms.

Mobility in soil

No information available

Other adverse effects

Do not release untreated into natural waters. No other adverse environmental effects

are expected.

13. DISPOSAL CONSIDERATIONS

Waste Disposal Method

Dispose of in accordance with local regulations.

Contaminated Packaging

Empty containers should be taken for local recycling, recovery or waste disposal.

14. TRANSPORT INFORMATION

UN Number: 1268

UN Proper Shipping Name: Petroleum products, N.O.S. (hexanes)

Transport Hazard Class(es)

Class: TDG: 3

US DOT: 3 IMDG: 3

Label(s): 3 Packing Group: Ш Marine Pollutant: Nο

Special precautions for user: None established

Transport in bulk according to Annex II of MARPOL73/78 and the IBC Code:

Not determined

PENETONE 4015P Page 6 of 6

15. REGULATORY INFORMATION

Canada (DSL/NDSL)

All ingredients contained in this product are in compliance with the Canadian Environmental Protection Act and are listed on the DSL or are exempt.

United States (TSCA)

All ingredients contained in this product are listed on the TSCA inventory or are exempt.

HMIS Information:

Health: 2 Flammability: 3 Reactivity: 0

16. OTHER INFORMATION

Preparation Date 19 April 2016 Revision Date 9 July 2025

Revision Note Revision 1 – Adjustments to Sections 1, 14, and 15

Disclaimer

The information provided on this MSDS is correct to the best of our knowledge, information and belief at the date of its publication. The information given is designed only as a guide for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered as a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other material or in any process, unless specified in the text.

End of SDS