

WEST B-3505

ADDITIVE FOR BOILER TREATMENT

WEST B-3505 contains a mixture of sequestering agent, dispersants and polymer which allows prevention of deposits in the boiler and in the purge lines.

Divalent and trivalent elements such as calcium, magnesium and iron will be sequestered and then dispersed, which will prevent their deposition and accumulation in the surface and bottom purge lines.

WEST B-3505 is specifically formulated for use in high heat transfer boilers.

FEATURES & BENEFITS

- Formulated to protect the steam boiler in the presence of hardness
- Contains sequestering agent and crystal modifiers
- Contains dispersants
- Contains a polymer
- Product contains a very effective defoamer for protection against foaming in the steam boiler
- Very low required dosage compared to competitors



DIRECTIONS FOR USE

Techniques

It is recommended to inject **WEST B-3505** directly into the make-up water tank. Soft water or water from the condensate return line should be used if you need to dilute **WEST B-3505** before injecting it.

A dosage between 25 and 60ppm is generally necessary to ensure adequate control of the deposit in the boiler and the drain lines.

WEST B-3505 ADDITIVE FOR BOILER TREATMENT

PHYSICAL PROPERTIES

Appearance	Clear, amber liquid
Odour	Sweet
Specific gravity @ 20°C	1.07
Viscosity	Not available
pH	12-13
Flash point (TCC)	Not applicable
Water solubility	Complete
Auto ignition temperature	Not available
Boiling point	>100°C
Freezing point	-10°C
Foaming tendency	Not applicable
Concentration monitoring techniques	Palintest ou PTSA
Rinsing	Not applicable

INCOMPATIBILITY

Not available

WAREHOUSING PRECAUTIONS

Keep containers tightly closed in a dry, cool and well-ventilated place

AVAILABLE SIZES

			
	20L (24Kg)		

IMPORTANT

Before using **WEST B-3505**, always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

FIRST AID MEASURES

Eye contact

Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician.

Skin contact

Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. Seek medical attention if irritation progresses and persists.

Inhalation

Remove person to fresh air and keep at rest in a position comfortable for breathing. Practice artificial respiration if the victim is no longer breathing. Seek immediate medical attention if breathing difficulties persist.

Ingestion

Do not induce vomiting. Drink 1 or 2 glasses of water. Call a physician or Poison Control Centre immediately. Never give anything by mouth to an unconscious person.

PERSONAL PROTECTION



WHMIS

