

WESTKLEEN 4115

LIQUID ALKALINE DEGREASER

WESTKLEEN 4115 is a concentrated, non-flammable, low foaming liquid alkaline detergent formulated for fast removal of water-based inks, grease, oil and grime in the paper converting and flexographic printing industries.

WESTKLEEN 4115 is recommended for use on flexographic anilox rolls, top print and bottom press rolls, and for circulation through anilox systems (roll, tray, ink pot and ink lines).

FEATURES & BENEFITS

- Highly concentrated
- Easy to use
- Diverse applications
- Safer than conventional solvents
- No fire or flash point
- Biodegradable
- Free rinsing
- Extremely cost effective
- Reduces cleanup time
- Can be used for many applications
- Safer for employees to use
- Leaves no film or residue



DIRECTIONS FOR USE

Use procedures

Surface to be cleaned	Recommended dilution	Procedure
Anilox System (Flush)	1:1 - 1:10	Place solution in ink pot and flush thoroughly through the system. Rinse with water.
Top Print & Bottom Press Rolls	1:5 - 1:10	Wipe or spray with solution. Wipe off with clean, damp cloth.
Press Exterior	1:5 - 1:10	Wipe or spray with solution. Wipe off with clean, damp cloth.
Dies	1:5 - 1:10	Wipe or spray with solution. Wipe off with clean, damp cloth.
Floors	1:1 - 1:10	Apply with mop, agitate. Remove with a clean mop or wet vac.

WESTKLEEN 4115 LIQUID ALKALINE DEGREASER

PHYSICAL PROPERTIES

Appearance	Clear, yellow liquid
Odour	Butyl solvent
Specific gravity @ 20°C	1.04
Viscosity	<10 cps
pH	13
Flash point (TCC)	None
Water solubility	Complete
Auto ignition temperature	None
Boiling point	100°C
Freezing point	Not available
Foaming tendency	Moderate
Concentration monitoring techniques	Electrical conductivity, titration
Rinsing	Excellent

INCOMPATIBILITY

Strong acids

WAREHOUSING PRECAUTIONS

Keep containers tightly closed in a dry, cool and well-ventilated place

AVAILABLE SIZES

			
4 X 4L	20L	205L	1000L



IMPORTANT

Before using **WESTKLEEN 4115**, always be sure to read and follow precautions and directions for use appearing on the product's container label, and on the safety data sheet (S.D.S).

FIRST AID MEASURES

Eye contact

Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor/physician.

Skin contact

Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse.

Inhalation

Remove person to fresh air and keep at rest in a position comfortable for breathing. Immediately call a POISON CENTER or doctor/physician.

Ingestion

Do not induce vomiting. Drink 1 or 2 glasses of water. Call a physician or Poison Control Centre immediately. Never give anything by mouth to an unconscious person.

PERSONAL PROTECTION



WHMIS

